## SCRATCH AND DENT APPRAISAL

APP # J819  $\checkmark$ LOCATION #45 AS IS Miami, OK. COMPLET **BOAT MAKE** Model HIN BACKGROUND INFORMATION GENERAL CONDITION GOOD FAIR POOR COMMENTS HULL UPHOLSTERY/SEATS GRAPHICS PAINT **DECKS** WINDSHIELD STEERING/ELEC TROLLING MOTOR **ACCESSORIES** MOTOR MAKE Model 2 SER 1 Model 1 BACKGROUND INFORMATION GOOD POOR COMMENTS GENERAL CONDITION **FAIR** NO MOTOR PAINT **PROP** POWER TRIM NO 🔻 LOWER UNIT WINTERIZED? MTR HRS: 0 TRAILER MAKE KARAVAN VIN 5KTBS2113MF575406 MODEL TRL,AL,SA,BRK,AW,SP:18LTS'21 Too old for production. No structual or mechanical defects found. **BACKGROUND** INFORMATION NO COSMETICS. SOLD AS IS. GENERAL CONDITION GOOD FAIR POOR COMMENTS **PAINT** 7 **TIRES** 1 LIGHTS 7 **BRAKES**  $\overline{\mathcal{A}}$ WINCH STAND  $\sqrt{}$ **BUNKS**