SCRATCH AND DENT APPRAISAL										
										APP #
										L9026
LOCATION		I FR	ANON			10	1	24 /	2022	AS IS
LOCATION					•	10	1	24 /	2022	
BOAT MAKE	RANGER Model RT-198 P					HIN RGR91135E919				
BACKGROUND	BOAT WAS REPURCHASED DUE TO ELECTROLYSIS CONCERNS									
INFORMATION	DID NOT FIND ANY STRAY CURRENT IN THE HULL, COOROSION SPOT STBD GUNNEL									
	NEAR CONSOLE,									
			2002	1			_		TO	
GENERAL CONDITION	GOOD	FAIR	POOR							014
										LOVV
UPHOLSTERY/SEATS GRAPHICS	✓ ✓			NU STR	ATU			I THE HU	JLL	
PAINT										
DECKS										
WINDSHIELD										
STEERING/ELEC										
TROLLING MOTOR										
ACCESSORIES										
MOTOR MAKE				Madal Q			206	51117		
	MERCORT	Model 1	150 PSX4			JER I	200	51117		
BACKGROUND	MOTOR H	HAS BEE	N RAN 65 H	IOURS						
INFORMATION										
GENERAL CONDITION	GOOD	FAIR	POOR				C	OMMEN	TS	
PAINT				MOTOR	RAN	65 HO			-	
PROP										
POWER TRIM										
LOWER UNIT				NO 🔻						
MTR HRS : 65	WINTERIZED?									
		MODEL				\ /II				0007
TRAILER MAKE	Ranger	MODEL	R1198P			VII	N.	7J5BBZ	J2XLF16	8837
BACKGROUND	TRAILR F	HAS BEEI	N PULLED D	DOWN TH	IE RO	AD, N	O ID	EA HOW	MANY	MILES
INFORMATION										
GENERAL CONDITIO	N GOOD	FAIR	POOR				0	OMMEN	TC	
PAINT				TRAILE	R HVO				110	
TIRES	✓ ✓									
LIGHTS	 ✓									
BRAKES										
WINCH STAND										
BUNKS	✓			1						