## SCRATCH AND DENT APPRAISAL

APP # G0327

LOCATION	MIDWAY						AS IS	
							COMPLET	
BOAT MAKE		Model			HIN			
BACKGROUND								
INFORMATION								
GENERAL CONDITION	GOOD	FAIR	POOR			COMME	NTS	
HULL			П			COMMI		
UPHOLSTERY/SEATS								
GRAPHICS								
PAINT								
DECKS								
WINDSHIELD								
STEERING/ELEC								
TROLLING MOTOR								
ACCESSORIES								
MOTOR MAKE		Model 1		Model 2	SEI	R 1		
BACKGROUND INFORMATION								
GENERAL CONDITION	GOOD	FAIR	POOR			COMME	NTS	
PAINT								
PROP								
POWER TRIM								
LOWER UNIT				NO 🔻				
HOURS		WINT	ERIZED	?no				
TRAILER MAKE	TRAILER MAKE MODEL 189 TRX VIN 1L83L6MB5PA000128							
		IVIODEL	109 1100			VIIV ILOGE	-01VID31 A000 120	
BACKGROUND INFORMATION								
GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS				
PAINT	<b>✓</b>			STAUS C				
TIRES	<b>✓</b>							
LIGHTS	7							
BRAKES	7							
WINCH STAND	7							
BUNKS	7							