## SCRATCH AND DENT APPRAISAL

APP # G0319

LOCATION		MIDWAY	<u>′</u>			. <u>—</u> —	AS IS COMPLET
BOAT MAKE		Model			HIN		
BACKGROUND							
INFORMATION							
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
HULL	GOOD	FAIR	POUR			COMMENTS	
UPHOLSTERY/SEATS		+ = +					
GRAPHICS		+					
PAINT		+					
DECKS		+					
WINDSHIELD		<b>+                                    </b>					
STEERING/ELEC		T					
TROLLING MOTOR							
ACCESSORIES							
MOTOR MAKE		Model 1		Model 2	SER 1		
BACKGROUND INFORMATION							
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
PAINT							
PROP							
POWER TRIM					1		
LOWER UNIT		$T \square T$		NO 🔻			
HOURS		WINT	ERIZED	?no			
TRAILER MAKE	MODEL 19 TRX				VIN 1L83L6NJ2NA005225		
BACKGROUND							
INFORMATION							
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
PAINT	7	$T \sqcap T$		STATU	SC		
TIRES	7						
LIGHTS	<b>✓</b>						
BRAKES	<b>✓</b>						
WINCH STAND	<b>✓</b>						
BUNKS	7						