## SCRATCH AND DENT APPRAISAL

APP #
G0331

LOCATION MIDWAY AS IS
COMPLET

BOAT MAKE Model HIN

							COMPLET
BOAT MAKE		Model			HIN		
BACKGROUND							
INFORMATION							
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
HULL							
UPHOLSTERY/SEATS							
GRAPHICS							
PAINT							
DECKS							
WINDSHIELD							
STEERING/ELEC							
TROLLING MOTOR							
ACCESSORIES							
MOTOR MAKE		_ Model 1		Model 2	SER 1		
BACKGROUND							
INFORMATION							
	· · · · · · · · · · · · · · · · · · ·		1				
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
PAINT	+	++-					
PROP TRIM	<del> </del>	+					
POWER TRIM	+	$+ \vdash \vdash$		NO 🔻			
LOWER UNIT HOURS	<del>                                     </del>	WINT	ERIZED				
HOURS	<u> </u>	VVIIVI	LNIZLD	:[IIO			
TRAILER MAKE		MODEL	186 FH		VII	1L83L6MC9I	NA005385
BACKGROUND							
INFORMATION							
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
PAINT		FAIR	FOOR	STATUS	S C	COMMENTS	
TIRES	✓ ✓	+		STATUS	, С		
LIGHTS	7	+					
BRAKES	7	+					
WINCH STAND	7	+					
BUNKS	7		H				
		1					
		1					
		1					