## SCRATCH AND DENT APPRAISAL

APP #
G0330

AS IS

LOCATION		MIDWA	<u> </u>				AS IS
							COMPLET
BOAT MAKE		Model			HIN		
BACKGROUND							
INFORMATION	-						
	-						
OFNEDAL CONDITION	0000	T END	D00D			COMMENTS	
GENERAL CONDITION HULL	GOOD	FAIR	POOR	+		COMMENTS	
UPHOLSTERY/SEATS		+					
GRAPHICS				1			
PAINT		+ ===					
DECKS		<b>+</b>		1			
WINDSHIELD							
STEERING/ELEC							
TROLLING MOTOR							
ACCESSORIES							
MOTOR MAKE		Model 1		Model 2	SER 1		
BACKGROUND							
INFORMATION							
	-						
				_		00141451450	
GENERAL CONDITION	GOOD	FAIR	POOR	+		COMMENTS	
PAINT		+					
PROP POWER TRIM							
LOWER UNIT	<del></del>	+		NO 🔻			
HOURS		WINT	ERIZED	2no			
		1		.1			
TRAILER MAKE		_MODEL	186 FH		VIN	1L83L6MC1	NA005400
BACKGROUND							
INFORMATION							
OFNEDAL CONDITION		T EAID	D00D	_		00141451450	
GENERAL CONDITION PAINT		FAIR	POOR	STATUS	0.0	COMMENTS	
TIRES	<b>✓</b>	+ + -		STATUS	5 C		
LIGHTS	7	+					
BRAKES		+					
WINCH STAND	7						
BUNKS				1			