## SCRATCH AND DENT APPRAISAL

APP # G0347

LOCATION MIDWAY							AS IS
BOAT MAKE		Model			. <u></u>		COMPLET
BOAT WARE		- Model			. ПП		
BACKGROUND							
INFORMATION							
GENERAL CONDITION	GOOD	FAIR	POOR	T		COMMENTS	
HULL						OOMMENTO	
UPHOLSTERY/SEATS							
GRAPHICS							
PAINT			H	1			
DECKS			H				
WINDSHIELD			H				
STEERING/ELEC			H				
TROLLING MOTOR			H				
ACCESSORIES							
MOTOR MAKE		Model 1		Model 2	SER <sup>2</sup>	1	
BACKGROUND INFORMATION							
GENERAL CONDITION	GOOD	FAIR	POOR	1		COMMENTS	
PAINT			П			OGIMILATIO	
PROP							
POWER TRIM							
LOWER UNIT				NO 🔻			
HOURS		WINT	ERIZED'	?no			
TRAILER MAKE MODEL 179 TRX					VI	N 1L83L6LA6NA0	005733
BACKGROUND INFORMATION							
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
PAINT	<b>V</b>			STATUS	S C		
TIRES	<b>✓</b>						
LIGHTS	<b>V</b>						
BRAKES							
WINCH STAND	<b>✓</b>						
BUNKS	✓ <u> </u>			1			