SCRATCH AND DENT APPRAISAL

APP # G0335

| LOCATION MIDWAY | | | | | | | ASIS |
|-------------------|----------|-------------------|-------------|----------|-------|--------------------|-----------|
| | | | | | | | COMPLET |
| BOAT MAKE | | Model | | | HIN | | |
| BACKGROUND | | | | | | | |
| INFORMATION | | | | | | | |
| | | | | | | | |
| GENERAL CONDITION | GOOD | FAIR | POOR | | | COMMENTS | |
| HULL | | | | | | | |
| UPHOLSTERY/SEATS | | | | | | | |
| GRAPHICS | | | | | | | |
| PAINT | | | | | | | |
| DECKS | | | | | | | |
| WINDSHIELD | | | | | | | |
| STEERING/ELEC | | | | | | | |
| TROLLING MOTOR | | | | | | | |
| ACCESSORIES | | | | | | | |
| MOTOR MAKE | | Model 1 | | Model 2 | SER · | 1 | |
| | | | | _ | | | |
| BACKGROUND | | | | | | | |
| INFORMATION | | | | | | | |
| | | | | | | | |
| GENERAL CONDITION | GOOD | FAIR | POOR | | | COMMENTS | |
| PAINT | | | | | | | |
| PROP | | | | | | | |
| POWER TRIM | | | | | | | |
| LOWER UNIT | | | | NO 🔻 | | | |
| HOURS | | WINT | ERIZED' | ?no | | | |
| TOURS | | | | | | | |
| TRAILER MAKE | | MODEL | 19 TRX | | V | IN <u>1L83L6NJ</u> | 9NA005853 |
| BACKGROUND | | | | | | | |
| INFORMATION | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| GENERAL CONDITION | | FAIR | POOR | 07.471.1 | | COMMENTS | |
| PAINT | I | $+ \vdash \vdash$ | \vdash | STATUS | S C | | |
| TIRES | ✓ | + | <u> </u> | | | | |
| LIGHTS | 7 | + - | <u> </u> | | | | |
| BRAKES | <u> </u> | $+ \vdash \vdash$ | | | | | |
| WINCH STAND | <u> </u> | + | | | | | |
| BUNKS | ✓ | | | | ı | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |