	SC	CRATCH AND [	DENT APPRAISAL	APP # GO345
LOCATION		MIDWAY		AS IS
BOAT MAKE		Model	HIN	
BACKGROUND INFORMATION				
GENERAL CONDITION	GOOD	FAIR POOR	COMMEN	TS
HULL				
UPHOLSTERY/SEATS				
GRAPHICS				
PAINT				
DECKS				
WINDSHIELD				
STEERING/ELEC				
TROLLING MOTOR				
ACCESSORIES				
MOTOR MAKE		Model 1	Model 2 SER 1	
BACKGROUND				
INFORMATION				
GENERAL CONDITION	GOOD	FAIR POOR	COMMEN	TS
PAINT				
PROP				
POWER TRIM				
LOWER UNIT			NO 🔻	
HOURS		WINTERIZED	?no	
TRAILER MAKE		MODEL 186 FH	VIN 1L83L6	MC3NA006192
BACKGROUND				
INFORMATION				
GENERAL CONDITION		FAIR POOR	COMMEN	TS
PAINT			STATUS C	
TIRES	✓			
LIGHTS	✓			
BRAKES	<b>√</b>			
WINCH STAND	I			
BUNKS				