SCRATCH AND DENT APPRAISAL

APP # G0328

LOCATION	MIDWAY						AS IS	
							COMPLET	
BOAT MAKE		Model			HIN			
BACKGROUND								
INFORMATION								
•								
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENT	S	
HULL			П			OOMMEN		
UPHOLSTERY/SEATS								
GRAPHICS								
PAINT								
DECKS								
WINDSHIELD								
STEERING/ELEC								
TROLLING MOTOR								
ACCESSORIES								
MOTOR MAKE		Model 1		Model 2	SEF	R 1		
BACKGROUND INFORMATION								
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENT	S	
PAINT								
PROP								
POWER TRIM								
LOWER UNIT				NO 🔻				
HOURS		WINT	ERIZED'	?no				
TRAILER MAKE	TRAILER MAKE MODEL 179 TRX VIN 1L83L6LA1NA006398							
BACKGROUND INFORMATION								
GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS				
PAINT	✓			STATU	SC			
TIRES	V							
LIGHTS	7							
BRAKES								
WINCH STAND	7							
BUNKS	V				•			