SCRATCH AND DENT APPRAISAL

APP # G0324

LOCATION MIDWAY					<u> </u>		AS IS
							COMPLET
BOAT MAKE		Model			HIN		
BACKGROUND							
INFORMATION							
GENERAL CONDITION	GOOD	FAIR	POOR	Ī		COMMENTS	3
HULL						COMMENT	
UPHOLSTERY/SEATS							
GRAPHICS							
PAINT							
DECKS							
WINDSHIELD							
STEERING/ELEC							
TROLLING MOTOR							
ACCESSORIES							
MOTOR MAKE		Model 1		Model 2	SER 1		
BACKGROUND							
INFORMATION							
INI ORIVIATION							
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	3
PAINT							
PROP							
POWER TRIM							
LOWER UNIT				NO 🔻			
HOURS		WINT	ERIZED'	?no			
TRAILER MAKE MODEL 20 TRX					VII	N <u>1L83L6PJ</u>	4NA006504
BACKGROUND							
INFORMATION							
OFNEDAL CONDITION	0000	T EAID	DOOD	Ī		OOMMENT.	
GENERAL CONDITION		FAIR	POOR	CTATU	0.0	COMMENTS	<u> </u>
PAINT	V	$+ \vdash \vdash$		STATUS	S C		
TIRES LIGHTS	V	+					
BRAKES	✓	+ + +					
WINCH STAND	✓	$+ \vdash \vdash$					
BUNKS	✓ ✓	+					
DUINNO	<u> </u>	+			I		
		I					