## SCRATCH AND DENT APPRAISAL

LOCATION MIDWAY AS IS COMPLET COMPLET

							COMPLET
BOAT MAKE		Model			HIN		
BACKGROUND							
INFORMATION							
INI ORWATION							
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
HULL							
UPHOLSTERY/SEATS							
GRAPHICS							
PAINT							
DECKS							
WINDSHIELD							
STEERING/ELEC							
TROLLING MOTOR				ļ			
ACCESSORIES							
MOTOR MAKE		_ Model 1		Model 2	SER 1		
BACKGROUND							
INFORMATION							
				1			
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
PAINT							
PROP		+					
POWER TRIM	<u> </u>	+		NO 🔻			
LOWER UNIT		10(11)					
HOURS		WINI	ERIZED'	no?			
TRAILER MAKE		MODEL	179 TRX		VIN	1L83L6LA1NA	006515
BACKGROUND							
INFORMATION							
GENERAL CONDITION		FAIR	POOR			COMMENTS	
PAINT	<b>V</b>			STATUS	С		
TIRES	7						
LIGHTS	<b>V</b>	<del></del>					
BRAKES							
WINCH STAND	<b>V</b>						
BUNKS	<b>V</b>			<u> </u>			