SCRATCH AND DENT APPRAISAL

LOCATION

MIDWAY

APP #
G0349

AS IS
COMPLET

							COMPLET
BOAT MAKE		Model			HIN		
BACKGROUND							
INFORMATION							
IN ONWATION							
				•			
GENERAL CONDITION	GOOD	FAIR	POOR			COMMENTS	
HULL		$+$ \vdash \vdash					
UPHOLSTERY/SEATS		+					
GRAPHICS		+					
PAINT		+					
DECKS	-	+					
WINDSHIELD	<u> </u>	+					
STEERING/ELEC		+					
TROLLING MOTOR							
ACCESSORIES							
MOTOR MAKE		_ Model 1		Model 2	SER 1_		
BACKGROUND							
INFORMATION							
CENEDAL CONDITION	COOD	LAID	DOOD			COMMENTS	
GENERAL CONDITION PAINT	GOOD	FAIR	POOR			COMMENTS	
PROP			-				
		+					
POWER TRIM	\vdash	++-	-	NO 🔻			
LOWER UNIT HOURS		\\\/ N T	ERIZED				
nouks		IVV I IV I I	ERIZED	riio			
TRAILER MAKE		MODEL	179 TRX		VIN	1L83L6LB2N	A006547
BACKGROUND							
INFORMATION							
OFNEDAL CONDITION	0000	LEMB	DOOD	T			
GENERAL CONDITION		FAIR	POOR		2.0	COMMENTS	
PAINT	✓	+		STSTUS	5 C		
TIRES	✓						
LIGHTS	✓	+					
BRAKES WINCH STAND		+ $+$ $+$ $ -$	-				
	✓			1			
BUNKS	V						
		1					