

SCRATCH AND DENT APPRAISAL

APP #

L9192

LOCATION

LEBANON

11 / 9 / 2023

AS IS

COMPLETE

BOAT MAKE TRACKER Model 250LE3S HIN BUJ27695C323

BACKGROUND INFORMATION RETURN BOAT
SEE INSPECTION LIST: FUEL IN TANK, PAINT DAMAGE, SHROUD SCUFFED
RIG KIT:340931

| GENERAL CONDITION | GOOD | FAIR | POOR | COMMENTS |
|-------------------|-------------------------------------|--------------------------|--------------------------|-----------------------------------|
| HULL | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | SEE INSPECTION LIST |
| UPHOLSTERY/SEATS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | S/S WING PAINT MISSING |
| GRAPHICS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | PAINT CHIPS ON DECK TRIM |
| PAINT | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | REAR SHROUD SCUFFED |
| DECKS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | REAR BED HITS CANOPY WHEN OPENING |
| WINDSHIELD | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| STEERING/ELEC | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| TROLLING MOTOR | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| ACCESSORIES | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |

MOTOR MAKE MERCURY Model 1 300L Model 2 _____ SER 1 3B405052

BACKGROUND INFORMATION MOTOR BEEN RAN 16.8 HOURS

| GENERAL CONDITION | GOOD | FAIR | POOR | COMMENTS |
|-------------------|-------------------------------------|--------------------------|--------------------------|---------------------------|
| PAINT | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | MOTOR BEEN RAN 16.8 HOURS |
| PROP | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| POWER TRIM | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| LOWER UNIT | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | NO ▼ |
| MTR HRS : 16.8 | W I N T E R I Z E D ? | | | |

TRAILER MAKE _____ MODEL T23R250LE3 VIN 7J513KU22PB001123

BACKGROUND INFORMATION TRAILER BEEN RAN DOWN THE ROAD

| GENERAL CONDITION | GOOD | FAIR | POOR | COMMENTS |
|-------------------|-------------------------------------|-------------------------------------|--------------------------|--------------------------------|
| PAINT | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | TRAILER BEEN RAN DOWN THE ROAD |
| TIRES | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| LIGHTS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| BRAKES | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| WINCH STAND | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| BUNKS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |