SCRATCH AND DENT APPRAISAL

APP # L9225

LOCATION	LEBANON					4	/	25 /	2024	-	✓
										COMPLET	TE 🗌
BOAT MAKE	RANGER	Model	198	HIN	RGR	2527	'3H122				
BACKGROUND	WARRANTY BOAT/REPLACED AT DEALER/HULL ISSUES (FIXED)										
INFORMATION	SEE INSPECTION LIST:PAINT SCRATCHES,BUBBLED FOAM ON ALL LIDS,										
	SOMETHING PUSHING THRU HULL TOWARDS BOW AND KEEL HULL ISSUES FIX								XED		
GENERAL CONDITION	GOOD	FAIR	POOR				(COMMEN	NTS		
HULL		7				S	EE II	NSPECT	ION LIST	•	
UPHOLSTERY/SEATS	7			PAINT S	CRAT	CHE	S ON	TRANS	OM,BOT	TOM P/S,G	UNNE
GRAPHICS		7		ALL LIDS FOAM BUBBLED							
PAINT		7		MOTOR, TRANSDUCER, TROLLING MOTOR TAKEN OFF							
DECKS				NO FISHING SEATS							
WINDSHIELD				NO WINDSHIELDS							
STEERING/ELEC				DECAL DAMAGE S/S							
TROLLING MOTOR											
ACCESSORIES											
MOTOR MAKE	MERCURY	Model 1		Model 2		SER	1				
BACKGROUND	NO MOTO	OR									
INFORMATION											
GENERAL CONDITION	GOOD	FAIR	POOR				(COMME	NTS		
PAINT				+							
PROP				+							
POWER TRIM											
LOWER UNIT				NO 🔻							
MTR HRS : 0	WINTERIZED?										
TDAILED MAKE		MODEL				\/	IN				
TRAILER MAKE		MODEL				. VI	IIN				
BACKGROUND	NO TRAIL	LER									
INFORMATION											
GENERAL CONDITIO	N GOOD	FAIR	POOR	1			(COMMEN	NTS		
PAINT											
TIRES				†							
LIGHTS											
BRAKES				1							
WINCH STAND				†							
BUNKS				1							
- · · · · -											