

SCRATCH AND DENT APPRAISAL

APP #

L9227

LOCATION

LEBANON

4 / 25 / 2024

AS IS



COMPLETE



BOAT MAKE TRACKER Model CLASSIC HIN BUJ45347F122

BACKGROUND INFORMATION WARRANTY BOAT/HULL SUNK IN
SEE INSPECTION LIST:DECAL DAMAGE,EXTRA HOLES IN GUNNEL,DECKS, CONSOLE
RIG KIT:

GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
HULL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	SEE INSPECTION LIST
UPHOLSTERY/SEATS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	EXTRA HOLES ON GUNNELS ,CONSOLE AND DECK
GRAPHICS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	DECAL DAMAGED P/S AND S/S
PAINT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	WATER MARKS ON BOAT
DECKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	SCRATCH IN PAINT ON GUNNELS
WINDSHIELD	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	NO FISHING SEATS
STEERING/ELEC	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
TROLLING MOTOR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
ACCESSORIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

MOTOR MAKE MERCURY Model 1 _____ Model 2 _____ SER 1 _____

BACKGROUND INFORMATION NO MOTOR
HOLES ON TRANSON WHERE MOTOR WAS MOUNTED AND TRANSDUCER
BOTH REMOVED OFF TRANSON

GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
PAINT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
PROP	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
POWER TRIM	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
LOWER UNIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	NO ▼
MTR HRS :	W I N T E R I Z E D ?			

TRAILER MAKE _____ MODEL T22BASSTRK VIN 7J511AH19NB001182

BACKGROUND INFORMATION TRAILER BEEN RAN DOWN THE ROAD

GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
PAINT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	TRAILER BEEN RAN DOWN THE ROAD
TIRES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
LIGHTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
BRAKES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
WINCH STAND	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
BUNKS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	