## SCRATCH AND DENT APPRAISAL

APP # L9244

LOCATION	LEBANON					6	/	5 /	2024	AS IS	<b>✓</b>
										COMPLE	TE _
BOAT MAKE	Ranger	Model	23RT19	8P.801	HIN	RGR	1140	2H223			
BACKGROUND	BOAT RE	PLACED	DUE TO C	RACKS II	N HULI	L. CR	ACKS	HAVE	BEEN RE	PAIRED	AND
INFORMATION	BRACING HAS BEEN ADDED, BOAT LEAK TESTED AND IS WATER TIGHT										
GENERAL CONDITION	GOOD	FAIR	POOR		COMMENTS						
HULL		7		•	,	SEE II	NSPE	CTION	LIST BEL	.OW	
UPHOLSTERY/SEATS	7			STRIPE	MISS	ING F	ROM	SIDES			
GRAPHICS				REPAIR	RPAIN	T SPO	OTS C	N BOT	TOM HUL	L	
PAINT		<b>V</b>									
DECKS		7									
WINDSHIELD	<b>V</b>										
STEERING/ELEC	<b>7</b>										
TROLLING MOTOR											
ACCESSORIES	<b>V</b>										
MOTOR MAKE	MERCURY	Model 1		Model 2		SER <sup>2</sup>	1				
BACKGROUND	NO MOT	OR									
INFORMATION											
05115511 00115151011											
GENERAL CONDITION	GOOD	FAIR	POOR	NO MO	TOD		C	OMMEN	115		
PAINT	+		-	NO MO	IOR						
PROP TRIM	+		+								
POWER TRIM	+  -  -		<del></del>	NO 🔻							
LOWER UNIT		VA/ I NI T	F D L Z F D								
MTR HRS : 0		VVIINI	ERIZED	?							
TRAILER MAKE		MODEL				VI	N _				
BACKGROUND	NO TRAI	LER.									
INFORMATION			ANTED WIL	L NEED 1	O ORI	DER N	NEW				
OFNEDAL COMPLETO		E 4 15	B00B					0141451	ITO.		
GENERAL CONDITIO	N GOOD	FAIR	POOR	NO TO	ED		C	OMMEN	VIS .		
PAINT	+ $+$ $-$			NO TRA			ITED	\A/II I \	EED TO	ODDED 1	15\4/
TIRES	$+$ $\vdash$ $\vdash$			IF IRAI	LEK IS	A VV A	NIED	vvill N	IEED IO	ORDER N	1⊏
LIGHTS	$+ \vdash -$										
BRAKES	$+$ $\downarrow$ $-$										
WINCH STAND	+			1							
BUNKS											