

SCRATCH AND DENT APPRAISAL

APP #

L9259

LOCATION

LEBANON

6 / 20 / 2024

AS IS

COMPLETE

BOAT MAKE RANGER Model 198P HIN RGR50967H324

BACKGROUND INFORMATION RETURN BOAT
SEE INSPECTION LIST:FUEL IN TANK, WEATHERED, SAT UNCOVERED AND USED
BEEN DERIGGED

GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
HULL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	SEE INSPECTION LIST
UPHOLSTERY/SEATS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	FUEL IN TANK
GRAPHICS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	SAT UNCOVERED AND USED
PAINT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	FLOOR AND SEATS WEATHERED
DECKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	RUB RAIL DAMAGED P/S AND S/S
WINDSHIELD	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	P/S STRIPE DAMAGE
STEERING/ELEC	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	TROLLING MOTOR BEEN REMOVED (HOLES)
TROLLING MOTOR	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
ACCESSORIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

MOTOR MAKE MERCURY Model 1 _____ Model 2 _____ SER 1 _____

BACKGROUND INFORMATION NO MOTOR
HAD ONE ON IT BUT BEEN REMOVED

GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
PAINT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
PROP	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
POWER TRIM	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
LOWER UNIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	NO ▼
MTR HRS : 0	W I N T E R I Z E D ?			

TRAILER MAKE _____ MODEL 24RT198P.200 VIN 7J512LM18RB001095

BACKGROUND INFORMATION TRAILER BEEN RAN DOWN THE ROAD

GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
PAINT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	TRAILER BEEN RAN DOWN THE ROAD
TIRES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
LIGHTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
BRAKES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
WINCH STAND	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
BUNKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	