SCRATCH AND DENT APPRAISAL

APP # L9250

LOCATION			6	/	12 /	2024	AS IS	✓			
					_					COMPLETE	
BOAT MAKE	TRACKER	Model	1036 JON		HIN E	BUJ4	4718	E425			
BACKGROUND	DENT S/S										
INFORMATION	SEE INSPECTION LIST: DENT S/S HULL ABOVE STRIPE										
OFNEDAL CONDITION	0000	EAID	BOOD	<u> </u>					ITO		
GENERAL CONDITION HULL	GOOD	FAIR	POOR			C E		OMMEN	ION LIS	<u> </u>	
				DENT							
UPHOLSTERY/SEATS	✓ <u> </u>			DENT	S/S HULI	_ ABI	OVE	STRIPE			
GRAPHICS	✓ <u> </u>										
PAINT DECKS											
WINDSHIELD											
STEERING/ELEC											
TROLLING MOTOR											
ACCESSORIES											
MOTOR MAKE	MERCURY	Model 1		Model 2		SFR 1					
BACKGROUND	NO MOTOR										
INFORMATION											
GENERAL CONDITION	GOOD	FAIR	POOR				С	OMMEN	ITS		
PAINT				NO MC	TOR						
PROP											
POWER TRIM											
LOWER UNIT				NO 🔻							
MTR HRS : 0		WINT	ERIZED	?							
TRAILER MAKE		MODEL				IIV	N .				
BACKGROUND	NO TRAIL	FR									
INFORMATION	110 110 11										
GENERAL CONDITIO	N GOOD	FAIR	POOR				C	OMMEN	ITS		
PAINT								J.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
TIRES				NO TR	AILER						
LIGHTS				1							
BRAKES											
WINCH STAND											
BUNKS											