

SCRATCH AND DENT APPRAISAL

APP #
L9269

LOCATION LEBANON

8 / 5 / 2024 AS IS

COMPLETE

BOAT MAKE TRACKER Model PRO-170 HIN BUJ57351A222

BACKGROUND INFORMATION BOAT REPLACED AT DEALER DUE TO HOLES DRILLED IN BOTTOM OF HULL DURING PRODUCTION. HOLES IN HULL HAVE BEEN WELDED

GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
HULL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	BOAT LOOKS GOOD
UPHOLSTERY/SEATS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	HASS A FEW SCUFFS IN PAINT PORT
GRAPHICS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	HOLES IN HULL HAVE BEEN WELDED
PAINT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
DECKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
WINDSHIELD	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
STEERING/ELEC	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
TROLLING MOTOR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
ACCESSORIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

MOTOR MAKE MERCURY Model 1 _____ Model 2 _____ SER 1 _____

BACKGROUND INFORMATION NO MOTOR

GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
PAINT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	NO MOTOR
PROP	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
POWER TRIM	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
LOWER UNIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	NO ▼
MTR HRS : 0	W I N T E R I Z E D ?			

TRAILER MAKE Trailstar MODEL T22PRO170 VIN 7J511BH17NB002014

BACKGROUND INFORMATION TRAILER HAS BEEN PULLED DOWN THE ROAD, NO IDEA HOW MANY MILES

GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
PAINT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	TRAILER HAS BEEN PULLED DOWN ROAD
TIRES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
LIGHTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
BRAKES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
WINCH STAND	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
BUNKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	