SCRATCH AND DENT APPRAISAL

APP # J882 $\overline{}$ LOCATION #45 AS IS Miami, OK. COMPLET 18500TF **BOAT MAKE** Tahoe Model HIN BUJ94152D818 BACKGROUND WARRANTY RETURN BOAT. GLASS PRINT AND SIGNS OF EARLY DEMOLDING. INFORMATION No Cosmetics. Sold As Is. GENERAL CONDITION GOOD FAIR POOR COMMENTS HULL 1 **EXTREMELY WEATHERED & STAINED** UPHOLSTERY/SEATS 1 GRAPHICS $\sqrt{}$ **PAINT** 1 **DECKS** 1 WINDSHIELD 7 STEERING/ELEC 1 TROLLING MOTOR NΑ **ACCESSORIES** MOTOR MAKE Model 1 4.5L 200HP Model 2 Mercury SER 1 2A584121 BACKGROUND INFORMATION No cosmetics. Sold as is. GOOD POOR GENERAL CONDITION **FAIR COMMENTS** PAINT 1 **PROP** $\sqrt{}$ POWER TRIM 1 NO 🔻 LOWER UNIT J WINTERIZED? MTR HRS: 0 TRAILER MAKE **WRMG** VIN 7J515DK29KB001007 MODEL TRL,500TIO.19 BLK OFW TAB2 STD **BACKGROUND** INFORMATION NO COSMETICS. SOLD AS IS: GENERAL CONDITION GOOD FAIR POOR COMMENTS **PAINT** 1 **TIRES** 7 LIGHTS 1 **BRAKES** NA WINCH STAND J **BUNKS**