SCRATCH AND DENT APPRAISAL

APP # L9279

LOCATION	CATION LEBANON						/	26 /		2024	_ A	SIS	<u> </u>
											CON	MPLETE	
BOAT MAKE	TRACKER	Model	1436		HIN	BUJ5	049	61425					
BACKGROUND	WRONG	PAINT/N	EW BOAT/I	NON MAT	CHING	3 PAIN	JT						
INFORMATION	SEE INSPECTION LIST:PAINTED WRONG COLOR RIG KIT:												
GENERAL CONDITION	GOOD	FAIR	POOR				(COMME	ENT	S			
HULL	7				SEE INSPECTION LIST								
UPHOLSTERY/SEATS	✓			PAINTE	PAINTED WRONG COLOR								
GRAPHICS	<			GUNNEL PAINT DAMAGE P/S									
PAINT		V		BOW PAINT DAMAGE									
DECKS													
WINDSHIELD													
STEERING/ELEC													
TROLLING MOTOR													
ACCESSORIES													
MOTOR MAKE	MERCURY	Model 1	N/A	Model 2		SER 1	N/A	A					
BACKGROUND	NO MOTO	OR .											
INFORMATION													
GENERAL CONDITION	GOOD	FAIR	POOR					COMME	=NIT	S			
PAINT				NO MO	TOR			OUNIVIE					
PROP		-	-	INO IVIO	IOI								
POWER TRIM													
LOWER UNIT		-		NO 🔻									
MTR HRS : 0		WINT	ERIZED	?									
				•									
TRAILER MAKE		MODEL	N/A			- VI	N	N/A					
BACKGROUND	NO TRAIL	_ER											
INFORMATION													
CENEDAL CONDITIO	N 000D	EAID	DOOD	1				2014145	NIT	<u> </u>			
GENERAL CONDITIO	N GOOD	FAIR	POOR	NO TRA	JI ED			COMME	<u>=N I 3</u>	5			
PAINT		-		NO TRA	MLEK								
TIRES		-	-										
LIGHTS		-	-										
BRAKES		-											
WINCH STAND BUNKS	+												
ביוווסםן				1									