## SCRATCH AND DENT APPRAISAL

APP # L9280

LOCATION	LEBANON				9	/	26 /	2024	ASIS
									COMPLETE
BOAT MAKE	TRACKER	Model	143	36	HIN BU	J50497	1425		
BACKGROUND INFORMATION	WRONG PAINT/NEW BOAT/NON MATCHING PAINT SEE INSPECTION LIST:PAINTED WRONG COLOR RIG KIT:								
GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS					
HULL	<b>✓</b>					SEE IN	SPECT	ION LIST	-
UPHOLSTERY/SEATS	<b>J</b>				D WRONG				
GRAPHICS	<b>I</b>			GUNNEL PAINT DAMAGE P/S AND S/S					
PAINT		<b>J</b>		BOW PA	AINT DAM	AGE			
DECKS									
WINDSHIELD									
STEERING/ELEC									
TROLLING MOTOR									
ACCESSORIES									
MOTOR MAKE	MERCURY	Model 1	N/A	Model 2	SEF	R 1 N/A	L		
BACKGROUND INFORMATION	NO MOTO	OR							
GENERAL CONDITION	GOOD	FAIR	POOR				OMMEN	JTS	
PAINT				NO MOT	OR .		OWNIVIE	110	
PROP				110 1110 1	<u> </u>				
POWER TRIM									
LOWER UNIT	$+$ $\vdash$ $\vdash$			NO 🔻					
MTR HRS : 0	WINTERIZED?								
TRAILER MAKE		MODEL	N/A		,	VIN	N/A		
BACKGROUND INFORMATION	NO TRAIL	ER							
GENERAL CONDITIO	GOOD	FAIR	POOR			C	OMMEN	NTS	
PAINT				NO TRA	ILER				
TIRES									
LIGHTS				1					
BRAKES				1					
WINCH STAND				1					
BUNKS				1					