SCRATCH AND DENT APPRAISAL

APP # **M000228**

LOCATION	NEW BERN			
				COMPLET
BOAT MAKE		Model		HIN:
BACKGROUND				
INFORMATION				
GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
HULL				
UPHOLSTERY/SEATS				
SKINS/GRAPHICS				
PAINT				
DECKS				
WINDSHIELD				
STEERING/ELEC				
TROLLING MOTOR				
ACCESSORIES				<u> </u>
MOTOR MAKE		_ Model 1		Model 2SER 1SER 2
BACKGROUND				
INFORMATION				
				001415150
GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
PAINT		$+$ \vdash \vdash		
PROP				
POWER TRIM				NO V
LOWER UNIT				
MOTOR HOURS 0		WINT	ERIZED	?
TRAILER MAKE		MODEL		363237 VIN 1L83LEVG5PA000702
BACKGROUND				
INFORMATION				
GENERAL CONDITION	GOOD	FAIR	POOR	COMMENTS
PAINT	<u> </u>			COMMENTO
TIRES				NO TIRES
LIGHTS	7			
BRAKES	\[\frac{1}{\sqrt{1}}\]			
WINCH STAND				MISSING
BUNKS				