## SCRATCH AND DENT APPRAISAL

APP # 137 2024 AS IS 🗵 LOCATION Ozark 13 9 / COMPLET **BOAT MAKE** Model HIN BACKGROUND INFORMATION GENERAL CONDITION GOOD FAIR POOR COMMENTS HULL UPHOLSTERY/SEATS GRAPHICS PAINT **DECKS** WINDSHIELD STEERING/ELEC TROLLING MOTOR **ACCESSORIES** MOTOR MAKE Model 1 Model 2 SER 1 BACKGROUND INFORMATION GOOD POOR COMMENTS GENERAL CONDITION FAIR NO MOTOR PAINT **PROP** POWER TRIM NO 🔻 LOWER UNIT WINTERIZED? MTR HRS: 0 TRAILER MAKE MODEL T24RT208.101 VIN 7J512PM29RB001056 Ranger missing fenders, missing winchstand, paint damage, missing hardware BACKGROUND TRANSPORT DAMAGE INFORMATION GENERAL CONDITION GOOD COMMENTS FAIR POOR **PAINT** 1 **TIRES**  $\overline{}$ LIGHTS 7 **BRAKES**  $\overline{\mathcal{A}}$ WINCH STAND J missing winchstand **BUNKS**