SCRATCH AND DENT APPRAISAL

APP # L9301

LOCATION		LEB	ANON	<u> </u>	12 /	11 /	2024 AS IS
							COMPLETE
BOAT MAKE	TRACKER	Model	175V	T HIN BI	UJ45928	3F425	
BACKGROUND	SHIPPING	G/ YARD	DAMAGE R	TURN BOAT			
INFORMATION	SEE INSPECTION LIST:FRONT HULL DENTED FROM ROLLER, STRIPE DAMAGE						
	RIG KIT:337858						
GENERAL CONDITION	GOOD	FAIR	POOR		C	OMMEN	TS
HULL		~			SEE IN	ISPECTI	ON LIST
UPHOLSTERY/SEATS	7			FRONT HULL DE	ENTED I	FROM RO	OLLER (WELDED PLATE)
GRAPHICS		V		STRIPE DAMAGE P/S AND S/S			
PAINT		V		SCRATCH ON S/S TRANSOM TOP ABOVE STICKER			
DECKS	✓			SCUFF/PAINTER MISSING P/S TRANSOM			
WINDSHIELD	V						
STEERING/ELEC	√						
TROLLING MOTOR	V						
ACCESSORIES	4						
MOTOR MAKE	MERCURY	Model 1	115EXLPT	Model 2 SE	ER 1 <u>3B6</u>	31507	
BACKGROUND	NEW MO	TOR					
INFORMATION	TIETT INC	TOIL					
IIII OIIIII/IIIII							
GENERAL CONDITION	GOOD	FAIR	POOR			OMMEN	TS
PAINT	✓			NEW MOTOR			
PROP	✓						
POWER TRIM	✓						
LOWER UNIT	✓			NO 🔻			
MTR HRS : 0		WINT	ERIZED				
TRAILER MAKE		MODEL	T25PGV17		VIN	7J511LJ	14SB001138
BACKGROUND	NEW TRA	All FR					
INFORMATION	11211 110	WEET C					
IN ORIVINATION							
	-						
GENERAL CONDITIO	N GOOD	FAIR	POOR		C	OMMEN	TS
PAINT	✓						
TIRES	✓			NEW TRAILER			
LIGHTS	V						
BRAKES							
WINCH STAND	✓						
BUNKS	✓						