## SCRATCH AND DENT APPRAISAL

APP # L9304

LOCATION LEBANON						12	/	16 /		2024	AS	IS 🖳
											COMF	PLETE [
BOAT MAKE	TRACKER	Model	el 1648		HIN	BUJ9	004	0L324				
BACKGROUND	RETURN	BOAT/N	ON CURRE	NT BOAT								
INFORMATION	SEE INSPECTION LIST: SHIFTER HANDLE FADED											
	RIG KIT:	LOTION	CEIOT: OF III	TEICHIA	DLL	MULL						
GENERAL CONDITION	GOOD	FAIR	POOR				(	COMMI	ENT	S		
HULL	\ \					SE	EE I	NSPEC	CTIC	N LIST		
UPHOLSTERY/SEATS	7			SHIFTE	R HAI	NDLE I	FAD	ED				
GRAPHICS	<											,
PAINT	\( \sqrt{ } \)											
DECKS	\ \ \											
WINDSHIELD												
STEERING/ELEC	\\											
TROLLING MOTOR												
ACCESSORIES												
MOTOR MAKE	MERCURY	Model 1		Model 2		SER 1						
BACKGROUND	NO MOTO	OR .										
INFORMATION												
CENEDAL CONDITION	COOD	EAID	DOOD					COMMI	ENIT	-0		
GENERAL CONDITION	GOOD	FAIR	POOR	NO MOT	-OB			COMM		<u>ა</u>		
PAINT PROP		-	-	INO IVIO	UK							
POWER TRIM		-										
		-		NO 🔻								
LOWER UNIT	+ $  -$	W I NI T	L L ERIZED									
MTR HRS : 0		VVIINI	EKIZED	ſ								
TRAILER MAKE		MODEL	T24U1648			VII	N	7J517	EF1	2RB00	1569	
BACKGROUND	TRAILER	BEEN R	AN DOWN	THE ROA	D							
INFORMATION												
				1								
GENERAL CONDITIO		FAIR	POOR				(	COMMI	ENT	S		
PAINT	✓											
TIRES	<b>1 2 3 3 3 3 3 3 3 3 3 3</b>			TRAILE	≺ REE	:N RAI	N D	JWN T	HEF	KUAD		
LIGHTS			<u> </u>									
BRAKES			<u> </u>									
WINCH STAND	✓ <b>/</b>											
BUNKS	<b>✓</b>											